	•	Approved For Release 20 Z 16 OCT 62	04/06/43555FIEUR SECR		20300070103-1 2 3	ROUTING  4  5
25X1	TO * DIRECTOR FROM *			ZE19I)		
	ACTION: OSA (1-2-3-4-5-6-7-8-9-1Ø) INFO 3 S/C (11)				ROUTINE	
		1637z 16 oct 62	(	(6)		IN 52Ø79
25X1	¥	11	HFO		CITE	25X1

FUEL LINE BELLOWS IN LEFT WHEEL WELL AREA. ROUGH ETIC 17 OCTOBER. AIRCRAFT NUMBER THREE SCHEDULED FOR 1500 HOUR AREA TIME TAKE OFF. ENGINES STARTED BUT DIFFICULTY DEVELOPED WITH NOSE WHEEL STEERING ON TAXI OUT. STEERING KEPT DISENGAGING AFTER APPROXIMATELY TWO TO THREE DEGREE TURN. FLIGHT CANCELLED. TENTATIVELY RESCHEDULED FOR 0730 HOURS AREA TIME TAKE OFF 16 OCTOBER 1962.

END OF MESSAGE

SECRET

GEOUP I
Excluded from substantic derngrading and declassification

REPRODUCTION BY OTHER THAN THE ISSUING OFFICE IS PROHIBITED. Copy No.